

高雄市路竹區公所重大工程成果報告

工程名稱	中正路 118 巷至中山路 1157 巷路面改善工程	施工期程	108 年 04 月 29 日~108 年 05 月 29 日
工程概述	路面龜裂嚴重，考量行車安全，將路面 AC 重新刨鋪。		
 A narrow alleyway with a severely cracked and uneven asphalt surface. The left side features a building with a corrugated metal wall, and the right side has a brick wall with some overgrown vegetation. The ground is dark and shows significant wear and tear.	 The same alleyway during the construction phase. The surface is being prepared, showing a rough, textured appearance. A utility pole stands on the left, and potted plants are visible on the right. The overall scene is one of active work.		
施工前照片	施工中照片		
 Another view of the alleyway during construction. The surface is a mix of old asphalt and new material being laid down. The surrounding buildings and vegetation are visible, showing the context of the project.	 The alleyway after the construction is complete. The surface is now a smooth, uniform dark asphalt, showing a significant improvement in road quality and safety. The surrounding environment remains the same.		
施工中照片	施工後照片		